

HAGS[®]

Inspiring all generations

Quotation

HAGS - SMP Playgrounds LTD 01757 293404

Menheniot Parish Council - Play Area PL14 3RE		R10331	DATE:		06/09/2022
DESCRIPTION		QTY	UNIT	RATE	TOTAL

Roundabout (Honeycomb Whirl) - Remove and replace the bearings	WICK SPARES	1	each	£495.00	£495.00
Turnstile - Remove and replace the top and bottom bearings	WICK SPARES	1	each	£178.50	£178.50
Leg Press - Remove and replace the seated leg as it has split on both sides	FAF-SPARES	1	each	£477.00	£477.00
Multi Play Unit - Replace the missing fixings on the slide barrier	I&MRFBS	1	each		
	I&MREPMAINS	1	each	£950.00	£950.00
Repaint the following equipment: x6 pieces of Fitness Equipment Junior Swing (Inside fenced area) Multi Play Junior Multi Play Toddler	I&MCONTRACTSS	1	each	£4,170.00	£4,170.00
Carry out the following wet pour repairs in black:	180-010	5	each	£35.00	£175.00
Junior Swing (Outside fenced area) - 1, 600mm x 650mm 1, 200mm x 300mm 1, 300mm x 150mm	180-000	5	each	£52.40	£262.00
Spring Horse - 350mm x 250mm	I&MREPMAINS	1	each	£600.00	£600.00
Nursey Rhyme Unit - 1.5sqm					
Toddler Swing - 400mm x 200mm					
Spring See-Saw - x4 areas 250mm x 300mm					
Entrance - 3lin m and 1, 800mm x 700mm 1, 200 x 350mm					

Please Note: Painting works cannot be carried out when the outside temperature is less than 10 celsius

This quotation is valid for 90 days

Prices based on unrestricted access with vehicle (large transit / tipper) access within 30 mtrs of site entrance

Prices given subject to full site survey

Errors & Omissions Excluded HAGS-SMP Ltd General Conditions of Sale apply

All rates and prices quoted are based on full job specification. If specification alters or quantities change the prices will alter

PLEASE NOTE THE ABOVE PRICES DO NOT INCLUDE VAT

£7,307.50